

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

Model: U320 SCSI to EIDE 8 CHL. (i80321)(6420)
For: SB-2813SI, SB-2812SI series.

Important notes:

- 1. Update from 1.36 and earlier firmware, Ethernet config must be saved again.**
- 2. Please update BOOT module first.**
 - (1) Upgrade Boot module: 6420BOOTxxxxx.bin**
 - (2) Upgrade firmware: 6420xxxxxx.bin**

	Last Version	New Version
Version No.	1.39 060308	1.42 061103
Date		January 10, 2007
New		1. Added multiple volume check at one time (HTTP only). 2. Added SCRUB bad block and REPAIR parity function. 3. Added Event and warning if incomplete RAID Set discovered. 4. Added completion aborted and stopped events for migration, rebuilding and initialization. 5. New rescue mode. 6. Added new LSI chip support (A3). 7. Added HDD timeout option (12, 17, 22, 27 and 32).
Fixed		
Modification		1. The LBA address is logged for reference when Power loss during migration, rebuilding and initialization. 2. Change the Voltage high limit to 5.4V for 5V.
Removed		