

**Proware Technology Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: U3 SCSI to EIDE 4 CHL. (i80303)(8630/89190)**

**For: SB-1430SI/DP-430SI Series.**

	<b>Last Version</b>	<b>New Version</b>
<b>Version No.</b>	<b>1.07a</b>	<b>1.08a</b>
<b>Date</b>		<b>June 9, 2009</b>
<b>New</b>		
<b>Fixed</b>		1. Fixed latest Array rebuilding address can not record to NVRAM.
<b>Modification</b>		
<b>Removed</b>		