

# Proware Technology Corp.

## Technical Support Team

### Firmware History

#### **For 903UxxxxS series**

##### 4.27A:

1. Fixed Terminal error when Scan fun start.

##### 4.26A ~ 4.24A:

1. Not released.

##### 4.23A:

1. Fixed the "Sun OS" and "LSI" error.

##### 4.22A:

1. Add 'Shutdown' option. The shutdown process will switch Write\_Buffer Off.

##### 4.21A:

1. Compatible to FreeBSD.

##### 4.20A:

1. Not released.

##### 4.19A:

1. Spin up the disk one by one.
2. Fix halt while switch host terminator from ON to OFF and there does not exist external scsi terminator.

##### 4.18A:

1. Support inquiry cmd serial page (page code = 0x80).
2. Compatible to SunPlus LCD module.
3. Support inquiry cmd with page code 0x00, 0x80, 0x83.
4. Reset RESERVE, RELEASE protocol after bus reset and msg bus reset.

##### 4.17A:

1. Test only.

##### 4.16A:

1. Enhance SCAN disk function.
2. Compatible to HP OnlineDiag utility.

##### 4.15A:

1. Fix SCAN disk function.

##### 4.14A:

1. Add SCAN disk function.

##### 4.13A:

1. Add Acer I2C interface.

# Proware Technology Corp.

## Technical Support Team

2. New password check.

4.12A:

1. Add terminator menu for disk channel.

4.11A:

1. Fixed the problem that only occurs at the previous version.

2. Fixed the controller will hang up while the host channel does not have any terminator and the on-board terminator is disable.

3. New password check.

4.10A:

1. Support TI 29c040 flash ROM

2. Fixed the host cannot find the RAID controller after abnormal shutdown.

3. Change firmware name from '1' to '4'.

1.09A:

1. Modify the reply of the mode sense command if the mode sense page does not exist.

1.08A:

1. Initial release.

2. Compatible to win2000.