

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

Model: U3 SCSI Redundant CTRL. (Active-Active)(80303)
For: SB2990D/SB9900D/SB4120D/SB9912D

	Last Version	New Version
Version No.	1.18	1.20
Date		February 17, 2006
New		1. Support new flash type SST39SF040 and AMIC29040A.
Fixed		1. Fixed the "Cmp cmd" selection bar position issue. 2. Fixed "Disk timeout" setting cannot be saved problem. 3. Fixed statistics and LCD messages inconsistency over two controllers. 4. Fixed rebuild hanging problem during hot-spare disk or fail-over. 5. Fixed host problem on FreeBSD4.1. 6. Fixed disk not found problem when speed sets to Ultra2 and lower.
Modification		1. Always use 115200 baud-rate for the MODEM port.
Removed		1. Remove the "Termination" information display of host channels.