

# Proware Technology Corp.

## Technical Support Team

### Software Release Notes

#### **Model: proNAS 1.3.XX**

**For:** EN-2803S3H-NQX / EN-2123S3H-NQX / SN-3163S3H-NQX / EN-2126JS3H-NQX  
EN-3166JS3H-NQX / SN-2803H-PDC / SN-3163H-QX / EN-3166JS3H-QX /  
EN-2126JS3H-QX / CDP-1600 / CDP-1200 / DP-500(LV-672) / DN-503AH /  
DN-503AH-PDC / EN-2803S6H-NQX / EN-3160S6H-PDC / EN-1403AH-ADC /  
EN-2126JS3H-PDC / EN-2800H-CM-R / EN-2800H-CM-S / EN-2800H-PDC-R /  
EN-2800H-PDC-S / EN-3166JS3H-NQX-6G / EN-2123AH-IDC / SN-3163S6H-NQX /  
EN-2800H-CM (with G41)

**Version: 1.3.05-SP3 Date: 2011/11/30 PM11:36**

#### **Release Note:**

##### **System**

NEW : G41 mother board support(EN3160S6H-PDC)

##### **VG manager**

Bug : VG Name can't contain dash symbol

##### **Account Manager**

Bug : user can't change user password

##### **System manager**

ADD: support CPU temperature email alert

BUG: Fixed an issue that that ftp upgrade list is always empty

NEW: Add snmpd.log in logrotate.

##### **Raid Manager**

ADD : support create RAID 6 and RAID 50 by HighPoint [2720,2740]

## Storage

BUG : Fixed an issue that pvresize not work after extend RAID, there's a

**limitation:**not support if original volume less 2T then extend over 2T.

BUG : Fixed an issue that VG can't be extended if disk device is

/dev/sdi,/dev/sdj, ....dev/sdz.

## Share manager

MOD : share of AUDIT and RECYCLE can't select the encryption lv in

share option manager

BUG : fixed the issue of audit and recycle did't updata data after edit in

share option manager

NEW: Add email event for rsync.

## LCD2USB

NEW : G41 mother board detect(EN3160S6H-PDC)

## HA

BUG: Fixed issues that config of http and webdav service not sync after fail-over.

## Service

MOD: Default anonymous\_enable change to NO in vsftpd.conf

## Network

MOD: Scan to detect NICs and bond device every time when NAS service start.

## Others

NEW: Support new model EN-2803S6H-SQX and EN-2123AH-SQX

NEW : G41 mother board detect(EN3160S6H-PDC)

Upgrade ethtool to version 2.6.36

NEW: add new HP RAID 2720 v1.0 driver to support raid6

Upgrade HP RAID 2740 v1.1 driver to support raid6

BUG :1957 upgrade igb driver to version 3.2.9

BUG:fixed old areca sas card when reboot can't find vg lv