

**Proware Technology Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: E-SATA/USB/1394 to SATA-2 4 CHL. (I80219)(5030)**  
**For: SB-1403AA/1403UA/1403WA,**  
**DP-500AA/503AA/503UA/503WA series.**

**Important notes:**

- 1. Please update BOOT module first.**
  - (1) Upgrade Boot module: 5030BOOTxxxxx.bin**
  - (2) Upgrade firmware: 5030xxxxxx.bin**

|                          | <b>Last Version</b> | <b>New Version YY/MM/DD</b>   |
|--------------------------|---------------------|---|
| <b>Version</b>           | <b>1.45 080602</b>  | <b>1.46 090106</b>  |
| <b>Boot Code Version</b> | <b>1.45 080314</b>  | <b>1.46 090106</b>  |
| <b>Release Date</b>      |                     | <b>June 11, 2009</b>  |
| <b>New</b>               |                     |   |
| <b>Fixed</b>             |                     | 1. Fixed NTP error after 2009.<br>2. Fixed Solaris 10 inquiry page 0x83 issue.<br>3. Fixed Solaris LBA overflow issue.<br>4. Improved SNMP agent request overflow issue.<br>5. Exclude super password via TELNET for security reason. |
| <b>Modification</b>      |                     | 1. Modified the LOGIN event from ERROR to WARNING.  |
| <b>Removed</b>           |                     |   |