

Proware Technology Corp.

Technical Support Team

Firmware History

For 903Uxxxx series

4.33A:

1. Add Performance menu for Sequential/Random setting.
2. Fixed VOD Key on/off timer

4.32A:

1. Fixed Terminal error when Scan fun start.

4.31A:

1. Fix 10000rpm disk startup bug.

4.30A:

1. Not released.

4.29A:

1. Not released.

4.28A:

1. Fixed the "Sun OS" and "LSI" error.

4.27A:

1. Modify shutdown process from stop response to just Write_Buffer Off.

4.26A:

1. Internal test, not released.
2. Add 'Shutdown' option.

4.25A:

1. Compatible to FreeBSD.

4.24A:

1. Not released.

4.23A:

1. Spin up the disk one by one.
2. Fix halt while switch host terminator from ON to OFF and there does not exist external scsi terminator.

4.22A:

1. Support inquiry cmd serial page (page code = 0x80).
2. Compatible to SunPlus LCD module.
3. Support inquiry cmd with page code 0x00, 0x80, 0x83.
4. Reset RESERVE, RELEASE protocol after bus reset and msg bus reset.

4.21A:

1. Test only.

Proware Technology Corp.

Technical Support Team

4.20A:

1. Enhance SCAN disk function.
2. Compatible to HP OnlineDiag utility.

4.19A:

1. Fix SCAN disk function.

4.18A:

1. Add SCAN disk function.

4.17A:

1. Password check.

4.16A:

1. Fixed the problem that only occurs at the previous version.
2. Fixed the controller will hang up while the host channel does not have any terminator and the on-board terminator is disable.
3. New password check.

4.15A:

1. Support TI 29c040 flash ROM
2. Fixed the host cannot find the RAID controller after abnormal shutdown.
3. Change firmware name from '1' to '4'.

1.14A:

1. Support TI TMS29c040 flash ROM.
2. Fixed GUI bug.
3. Remove unsupported command print out.

1.13A:

1. Add terminator menu for disk channel.
2. Add Acer I2C interface.

1.12A:

1. Test only.

1.11A:

1. Compatible to win2000.

1.10A:

1. Testing only.

1.09A:

1. Modify the reply of the mode sense command if the mode sense page does not exist.

1.08A:

1. Fix Stripe Size cannot modify.
2. Fix show "Warn Femp" to "Warn Temp".

Proware Technology Corp.

Technical Support Team

1.07A:

1. Compatible to QLOGIC SAFTE chip.

1.06A:

1. Fixed "repeat array check" menu error.
2. Fixed "expand array" menu error.
3. Fixed "reinit array" menu error.
4. Fixed SAFTE fan and temperature message error.

1.05A:

1. Support ASPI GUI interface.
2. Fix "Array Check" menu bug.
4. Support Disk Channel "Start Cmd" menu.

1.04A:

1. Test only.

1.03A:

1. Add GUI protocol.

1.02A:

1. Fix Quantum Viking II SCA restart issue.

1.01A:

1. Test only.

1.00A:

1. Initial release
2. Support 3 or 4 CHL.