

**UNIFOSA Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: SASIII to SASIII /SATA3 16/24 CHL. JBOD**  
**For: EP-2126J1/JD1-SCSC, EP-3166J1/JD1-SCSC, EP-2246J/JD-SCSC, EP-4246J/JD-SCSC, EN-2126JSC-xxx, EN3166JSC-xxx Series.**

**Important notes:**

- 1. Upgrade firmware: sas3xfwxxx.fw**

	<b>Last Version</b>	<b>New Version</b>
<b>Version</b>	0.0.21	0.0.23
<b>Release Date</b>	MAR 12,2018	JUL 20,2018
<b>New</b>	1. Add retry count and delay time for 4U24bay Slot19/20	1. Add the CLI Nick Name setting.
<b>Fixed</b>		1. After modifying the fan level, fans 3 fans 4 have no fixed speed problem.
<b>Modification</b>		<ol style="list-style-type: none"> <li>1. Modify the slot &amp; temp ses string and cancel the SLOT 01 space.</li> <li>2. Modify page 1 message RltbProclD, NumProc.</li> <li>3. The Routing type is changed from "S" to "T".</li> <li>4. Temperature &amp; voltage detection retry is changed from 3 times to 10 times, once every 4 seconds, and the "0xFF" error code is ignored.</li> </ol>
<b>Removed</b>		