

**Proware Technology Corp.**  
**Technical Support Team**  
*Proware Technology Corp. 2009*

**Firmware Release Notes**

**Model: EPICA PSUN Series (80331-500)**

**For: EP-3166-SA3, EP-2126-SA3, EP-2806-SA3, EN-3166H-xxx,  
EN-2126H-xxx, EN-2806H-xxx Series.**

**Important notes:**

**1. Upgrade firmware: proSUN\_1.27.gz**

	<b>Last Version</b>	<b>New Version</b>
<b>Version</b>	<b>1.25</b>	<b>1.27</b>
<b>Release Date</b>		<b>December 3, 2009</b>
<b>proRAIDMgr Version</b>	<b>1.34</b>	<b>1.34</b>
<b>New</b>		
<b>Fixed</b>		<ol style="list-style-type: none"><li>1. Fixed WD15EADS-00P8B0 WD10EADS-00M2B0 Detection and kick off in initialize issue.</li><li>2. Fixed IO running long time will stop.</li></ol>
<b>Modification</b>		
<b>Removed</b>		