

Proware Technology Corp.

Technical Notification

February 1, 2006

DP-405CI / SB-2805CI USB2.0 and IEEE1394b combo system.

1. RedHat 9 or Kernel 2.4.x

The firmware v1.0.7 for Oxford OXUF922 combo chip have some compatibility issue under Linux kernel 2.4.x. If you got trouble to use, please contact PROWARE to roll back the firmware to v1.0.5.

2. Fedora Core 4 or Kernel 2.6.1x

The Oxford OXUF922 combo chip has some compatibility issue under Linux kernel 2.6.1x. The OXUF922 firmware does not support the SCSI command 'REPORT LUN (0xA0)'. Please follow the documents to solve this issue for your system.

3. Reference Documents

(1) SB-2805CI -> 5013-138-lnx261x.pdf

(2) DP-405CI -> 5014-138-lnx261x.pdf