

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: EIDE to EIDE 8 CHL. (5013)

For: SN-2805P/SNi-2805/SB-2805CI series.

Important notes:

- 1. Please update BOOT module before upgrade this version.
5013BOOTxxxxx -> 5013xxxxxx.**

| | Last Version | New Version |
|---------------------|---------------------|--|
| Version No. | 1.33 040909 | 1.36 050725 |
| Date | | August 23, 2005 |
| New | | |
| Fixed | | 1. Fixed Mac OS X v10.4.x issue. 2. Fixed FAN detect issue. |
| Modification | | |
| Removed | | |