

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: E-SATA to USB2.0+SATA-2 4 CHL. (M88F5)(5020)
For: DP-403UA / SP-403AA / SB-1413AA(UA) / SP-1413AA
series.

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 5020BOOTxxxxx.bin**
 - (2) Upgrade firmware: 5020xxxxxx.bin**

	Last Version	New Version
Version	NA	1.45 080626
Boot Code	NA	1.45 080314
Date		July 31, 2008
New		1. Initial release.
Fixed		
Modification		
Removed		