

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: eSATA / IDE to SATA 4 CHL. (Marvell 88F5182) (5020)
For: DP-403UA, DP-403UA-R, SB-1413UA

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 5020BOOT-xxxxx.bin**
 - (2) Upgrade firmware: 5020-xxxxxx.bin**

| | Last Version | New Version |
|--------------------------|------------------------|---------------------------|
| Version | 1.47 2009-08-20 | 1.48 2010-01-12 |
| Boot Code Version | 1.47 2009-06-25 | 1.48 2010-01-04 |
| Release Date | JUL 28, 2009 | Apr 09, 2010 |
| New | | |
| Fixed | | 1. Add support DP-403UA-R |
| Modification | | |
| Removed | | |