

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: e-SATA / USB2.0 to SATA 8 CHL (Marvell 88F5182) (5060)
For: SB-2803UA/WA series.

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 5060BOOT-xxxxx.bin**
 - (2) Upgrade firmware: 5060-xxxxxx.bin**

	Last Version	New Version
Version	1.47 2009-08-20	1.48 2010-02-03
Boot Code Version	1.47 2009-08-174	1.48 2010-01-04
Release Date		MAR 25, 2010
New		1. Adding Iscsi / AoE protocol function by Rlink port
Fixed		
Modification		1. Channel Driver ID mapping
Removed		