

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: SCSI to SATA-2 4 CHL. (I80321) (6310)

For: SB-1403-SA3 / SB-4103E-SA3 /SB-1403E-SA3-R series.

Important notes:

1. Please update BOOT module first.

(1) Upgrade Boot module: 6310BOOT-xxxxx.bin

(2) Upgrade firmware: 6310-xxxxxx.bin

| | Last Version | New Version |
|--------------------------|---------------------|--|
| Version | 1.46 090106 | 1.48 2010-01-04 |
| Boot Code Version | 1.46 090106 | 1.48 2010-01-04 |
| Release Date | Arp 27, 2009 | Apr 30, 2010 |
| New | | 1. Add CheckChannel to errorHandler for Marvell 6081 |
| Fixed | | |
| Modification | | |
| Removed | | |