

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: SCSI to SATA-2 8 CHL. (I80321) (6320)
For: SB-2803SA series.

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 6320BOOT-xxx-xxxxxxxxx.bin**
 - (2) Upgrade firmware: 6320-xxx-xxxxxxxxx.bin**

	Last Version	New Version
Version	1.46 2009-04-21	1.48 2010-01-04
Boot Code Version	1.46 2009-01-06	1.46 2010-01-04
Release Date	JUN 12, 2009	MAY 05, 2010
New		1. Add CheckChannel to errorHandler for Marvell 6081.
Fixed		
Modification		
Removed		