

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: SCSI U320 to SATA-2 16 CHL. (I80321) (6330)
For: SB-2123SA series.

Important notes:

1. Please update BOOT module first.

(1) Upgrade Boot module: 6330BOOT-xxx-xxxxxxxxx.bin

(2) Upgrade firmware: 6330-xxx-xxxxxxxxx.bin

	Last Version	New Version
Version	1.46 2009-01-06	1.48 2010-01-04
Boot Code Version	1.46 2009-01-06	1.48 2010-01-04
Release Date	MAR 09, 2009	APR 26, 2010
New		1.Add CheckChannel to errorHandler for Marvell 6081.
Fixed		
Modification		
Removed		