

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

**Model: U320 SCSI to S-ATA 12 CHL. (i80321)(6330_4)(4FANs)
 For: SB-2125SA series.**

Important notes:

- 1. Please update BOOT module before upgrade this version.**
 - (1) Upgrade Boot module: 6330_4BOOTxxxxx.bin**
 - (2) Upgrade firmware: 6330_4xxxxxx.bin**

	Previous Version	New Version YYMMDD
Version	1.45 080410	1.46 090203
Boot Code version	1.45 080314	1.46 090106
Release Date		March 13, 2009
New		1. Added display of IU status.
Fixed		1. Fixed NTP error after 2009. 2. Fixed Solaris 10 inquiry page 0x83 issue. 3. Fixed Solaris LBA overflow issue. 4. Fixed ATTO U320 SCSI issue. 5. Improved SNMP agent request overflow issue. 6. Exclude super password via TELNET for security reason.
Modification		1. Modified the LOGIN event from ERROR to WARNING.
Removed		