

**Proware Technology Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: U320 SCSI to EIDE 16 CHL. (80321)(6460)**  
**For: SB-3163SI series.**

**Important notes:**

- 1. Update from 1.36 and earlier firmware, Ethernet config must be saved again.**
- 2. Please update BOOT module first.**
  - (1) Upgrade Boot module: 6460BOOTxxxxx.bin**
  - (2) Upgrade firmware: 6460xxxxxx.bin**

	<b>Last Version</b>	<b>New Version</b>
<b>Version No.</b>	<b>1.38 051123</b>	<b>1.39 060309</b>
<b>Date</b>		<b>April 13, 2006</b>
<b>New</b>		1. Added Stagger power on control function. 2. Added RAID 1(1+0) with initialization function.
<b>Fixed</b>		1. Fixed Ethernet problem (Browser and Telnet can not connect). 2. Fixed Hitachi 500G HDS725050KLAT80 issue.
<b>Modification</b>		1. Display SMART status in drive status. 2. Mail SMTP port settable.
<b>Removed</b>		