

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

Model: SAS to SATA-2 8 CHL. (I80321) (6520)

For: SB-2803-S3A3 series.

Important notes:

1. Please update BOOT module first.

(1) Upgrade Boot module: 6520BOOT-xxx-xxxxxxx.bin

(2) Upgrade firmware: 6520-xxx-xxxxxxx.bin

(3) Upgrade MPT firmware: 1064A4MPT-1.26.0.0.BIN

	Last Version	New Version
Version	1.46 2009-04-21	1.48 2010-02-01
Boot Code Version	1.46 2009-01-06	1.46 2010-01-04
MPT version	1064A4MPT-1.26.0.0	1064A4MPT-1.26.0.0
Release Date	JUN 12, 2009	APR 26, 2010
New		1. Add CheckChannel to errorHandler for Marvell 6081. 2. Add Support Microsoft Windows Server 2008 Failover Cluster.
Fixed		
Modification		
Removed		