

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: SAS3G to SATA-2 16 CHL. (I80321)(6560)
For: SB-3163-S3A3 series.

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 6560BOOT-xxxxx.bin**
 - (2) Upgrade firmware: 6560-xxxxxx.bin**
 - (3) Upgrade MPT firmware: 1064A4MPT-xxxxx.bin**

	Last Version	New Version
Version	1.45 080314	1.46 090421
Boot Code Version	1.45 080314	1.46 090106
MPT Version	1064A4-0.17.96.18	1064A4-1.26.0.0
Release Date		May 8, 2009
New		
Fixed		1. Fixed NTP error after 2009. 2. Fixed Solaris 10 inquiry page 0x83 issue. 3. Fixed Solaris LBA overflow issue. 4. Improved SNMP agent request overflow issue. 5. Exclude super password via TELNET for security reason.
Modification		1. Modified the LOGIN event from ERROR to WARNING.
Removed		