

**Proware Technology Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: SAS 3Gb/s to SATA-2 4/8/12/16 CHL. (IOP348) (6573)**  
**For: EP-1403-S3A3 / EP-2803E1-S3A3 / SB-2123E1-S3A3 /**  
**SB-3163E1-S3A3 / EP-T803E1-S3A3 series.**

**Important notes:**

- 1. Please update BOOT module first.**
  - (1) Upgrade Boot module: 6573BOOT-xxxxx.bin**
  - (2) Upgrade firmware: 6573-xxxxxx.bin**
  - (3) Upgrade MPT firmware: 1064A4MPT-x.xx.xx.xx.bin**

|                     | <b>Last Version</b>         | <b>New Version</b>          |
|---------------------|-----------------------------|-----------------------------|
| <b>FW Version</b>   | <b>1.49 2011-01-26</b>      | <b>1.49 2011-04-14</b>      |
| <b>Boot Version</b> | <b>1.49 2011-01-26</b>      | <b>1.49 2011-04-14</b>      |
| <b>MPT Version</b>  | <b>1064A4MPT-0.17.96.18</b> | <b>1064A4MPT-0.17.96.18</b> |
| <b>Release Date</b> | <b>Feb 22, 2011</b>         | <b>May 16, 2011</b>         |
| <b>New</b>          | 1. Formal Release.          |                             |
| <b>Fixed</b>        |                             | 1. Fixed SATAIII issue      |
| <b>Modification</b> |                             |                             |
| <b>Removed</b>      |                             |                             |