

**Proware Technology Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: U2 SCSI to EIDE 6 CHL. (486)**

**For: DataPlum/Mini-L, PRO-DP X, R3000IL Series**

	<b>Last Version</b>	<b>New Version</b>
<b>Version No.</b>	<b>2.1U</b>	<b>2.1W</b>
<b>Date</b>	<b>November 14, 2001</b>	<b>December 19, 2001</b>
<b>New</b>		
<b>Fixed</b>		1. Fix potential failure of host channel detection. (8100)
<b>Modification</b>		1. Too many HDD fail halt the RAID.
<b>Removed</b>		