

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

Model: SAS to SAS /SATA 12/16/42 CHL (Intel 81341)
For: SB-2123-S3S3 / SB-3163S-S3S3 / EP-2123S-S3S3 /EP-3163S-S3S3 / EP-2243-S3S3 / EP-4423S-S3S3 series.

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 8360BOOT-xxxxx.bin**
 - (2) Upgrade firmware: 8360-xxxxxx.bin**

	Last Version	New Version
Version	1.47 2009-08-18	1.48 2010-01-12
Boot Code Version	1.47 2009-06-26	1.48 2010-01-12
Release Date	Dec 17, 2009	May 17, 2010
New		<ol style="list-style-type: none"> 1. Add Disk Power cycle Function (Excluded SB-2123-S3S3). 2. Add Display "ENC#3 SES2Device" timeout if SES2 service timeout.
Fixed		
Modification		<ol style="list-style-type: none"> 1. Cannot Expand RaidSet "Conatins" Raid30/50/60 volume Word Modify to "Contains" instead.
Removed		