

Proware Technology Corp.  
Technical Support Team  
Firmware Release Notes

**Model: E-SATA/USB/1394 to SATA-2 4 CHL. (I80219)(ARC5030)**  
**For: DP-500AA, DP-503AA/503UA/503WA series.**

**Important notes:**

**1. Please update BOOT module first.**

**(1) Upgrade Boot module: ARC5030BOOTxxxxx.bin**

**(2) Upgrade firmware: ARC5030xxxxxx.bin**

	<b>Last Version</b>	<b>New Version YY/MM/DD</b>
<b>Version</b>	<b>1.45 080314</b>	<b>1.46 090106</b>
<b>Boot Code Version</b>	<b>1.45 080314</b>	<b>1.46 090106</b>
<b>Release Date</b>		<b>June 11, 2009</b>
<b>New</b>		
<b>Fixed</b>		1. Fixed NTP error after 2009. 2. Fixed Solaris 10 inquiry page 0x83 issue. 3. Fixed Solaris LBA overflow issue. 4. Improved SNMP agent request overflow issue. 5. Exclude super password via TELNET for security reason.
<b>Modification</b>		1. Modified the LOGIN event from ERROR to WARNING.
<b>Removed</b>		