

**Proware Technology Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: EIDE to EIDE 8 CHL. (5013)**  
**For: SN-2805P/SNi-2805/SB-2805CI series.**

**Important notes:**

- 1. Please update BOOT module before upgrade this version.  
5013BOOTxxxxx -> 5013xxxxxx.**

	<b>Last Version</b>	<b>New Version</b>
<b>Version No.</b>	<b>1.33 040909</b>	<b>1.36 050725</b>
<b>Date</b>		<b>August 23, 2005</b>
<b>New</b>		
<b>Fixed</b>		1. Fixed Mac OS X v10.4.x issue. 2. Fixed FAN detect issue.
<b>Modification</b>		
<b>Removed</b>		