

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

**Model: U320 SCSI/FC2G to Serial ATA 8 CHL.
 (i80321-600)(89200)
 For: SB-2808SA(T)/SI/FA(T)/FI Series.**

| | Last Version | New Version |
|---------------------|---------------------|---|
| Version No. | 1.05a | 1.06a |
| Date | | August 29, 2005 |
| New | | |
| Fixed | | 1. Fixed Host cannot access when Array with online-init is in progress. 2. Fixed PCI or SATA error when Array 1 is performing online-init and concurrently creating Array 2. FC: 1. Fixed Dual FC problem on Mac OS X 10.4. |
| Modification | | 1. Clear warning message automatically when BBM temperature is less than 45°C. |
| Removed | | |