

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

Model: SATA-2 to SATA-2 2 CHL.

For: DF-7506 series.

Important notes:

- 1. Upgrade firmware: Sil57x3_11576.bin**

	Last Version	New Version
Version	1.1596	1.1598
Release Date	NOV 24, 2009	OCT 13, 2011
New		
Fixed	<ol style="list-style-type: none"> 1. Fix to prevent a false alarm while HDDs are spinning, add 1minute delay. 2. Fix to support maximum seek time exceeding 11 seconds 3. Fix Hot-plug/unplug issue, that in some case RAID1 did not continue. 	<ol style="list-style-type: none"> 1. Enhanced SSD support to include 127GB or smaller devices. 2. Increased Config Disk timeout to 9 seconds to allow HDDs needed spin-up time.
Modification	<ol style="list-style-type: none"> 1. Enhance DF-7506 to support RAID volumes greater than 2TB capacity. 	
Removed		