

**UNIFOSA Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: SASII to SASII /SATA2 12/16/24 CHL. JBOD (LSI SAS 2x36)**  
**For: EP-2126J1/JD1-S6S6 / EP-3166J1/JD1-S6S6**  
**EP-2246J/JD-S6S6 / EP-4246JD-S6S6 Series.**

**Important notes:**

- 1. Upgrade firmware: sas2xfwxxx.fw**

|                     | <b>Last Version</b>  | <b>New Version</b>  |
|---------------------|--|---|
| <b>Version</b>      | 0.0.32   | 0.0.33  |
| <b>Release Date</b> | MAY 2,2014   | SEP 12,2014   |
| <b>New</b>          | <ol style="list-style-type: none"><li>1. Fix SAS Link Port light.</li><li>2. Add Support EP-4246J/JD-S6S6.</li><li>3. Support Windows 2012 / 2012 R2 Certification</li></ol> | <ol style="list-style-type: none"><li>1. Add EP-4246J/JD-S6S6.fan define.</li></ol> |
| <b>Fixed</b>        |  |   |
| <b>Modification</b> |  |   |
| <b>Removed</b>      |  |   |