

**UNIFOSA CORP.**  
**Technical Support Team**  
**Software Release Notes**

Model: proNAS 3.1.XX / 3.2.XX

For: EN-2123S6T-RQX / EN-3163S6T-RQX / EN-2126JS6T-SQX /  
EN-3166JS6T-SQX / EN-2120A6T-PDC / EN-3160A6T-PDC /  
EN-2800S6T-CM / DN-500A6T-CM / DN-500A6T-CQC /  
EN-1400A6T-CQC / EN-2126JSCT-SQX / EN-3166JSCT-SQX /  
EN-3166JS6T-RQX / EN-3166JSCT-RQX

<b>3.2.00SP1(2018-4-24 15:29)</b>	
<b>Release Date</b>	MAY 4, 2018
<b>Module</b>	Change Note
<b>Storage Manager</b>	<ul style="list-style-type: none"><li>• BUG Fixed volume extended size is not correct when volume size extend over 95% of total volume group size</li><li>• BUG Fixed M/B Asrock E3C224-4L and 12G backboard and 9260-4i , slot id would be shifted.</li></ul>