

**Proware Technology Corp.**  
**Technical Support Team**  
**Firmware Release Notes**

**Model: eSATA / IDE to SATA 4 CHL. (I80219) (5030)**  
**For: SB-1403AA / SB-1403UA / SB-1403WA series.**

**Important notes:**

- 1. Please update BOOT module first.**
  - (1) Upgrade Boot module: 5030BOOT-xxxxx.bin**
  - (2) Upgrade firmware: 5030-xxxxxx.bin**

	<b>Last Version</b>	<b>New Version</b>
<b>Version</b>	<b>1.46 090106</b>	<b>1.48 2010-01-04</b>
<b>Boot Code Version</b>	<b>1.46 090106</b>	<b>1.48 2010-01-04</b>
<b>Release Date</b>	Jul 29, 2009	<b>May 14, 2010</b>
<b>New</b>		1. Add CheckChannel to errorHandler for Marvell 6081
<b>Fixed</b>		
<b>Modification</b>		
<b>Removed</b>		