

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: SAS 6Gb/s to SAS 6Gb/s 8 CHL (LSI 2116)
For: EP-T803-S6S6, EP-2803-S6S6 series.

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 8040BOOT-xxxxx.bin**
 - (2) Upgrade firmware: 8040-xxxxxx.bin**

	Last Version	New Version
Version	1.48 2010-11-01	1.49 2011-06-17
Boot Code Version	1.48 2010-11-01	1.49 2011-06-17
Release Date	Dec 31, 2010	JUL 15, 2011
New	1. Formal release.	1. Add SAS Chip information function..
Fixed		1. Fixed windows server 2008 cluster problem.
Modification		1. Improve daisy chain EP-4423J-S6S6 enclosure sequence.
Removed		