

UNIFOSA Corp.
Technical Support Team
Firmware Release Notes

Model: SASII to SASII /SATAIII 12/16/42/64 CHL (LSISAS2116)
For: EP-2123-S6S6 / EP-3163-S6S6 / EP-2243-S6S6 / EP-4423-S6S6
/ EP-4643-S6S6 / SB-2123-S6S6 / SB-3163-S6S6 series.

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 8066BOOT-xxxxx.bin**
 - (2) Upgrade firmware: 8066-xxxxxx.bin**
 - (3) Upgrade MBR Firmware: 8066MBR0-xxxxxxxxx.bin**
 - (4) Upgrade Expander firmware:8016-x.xx.xx.xx-xxxxxxxxx.fw**
 - (5) Upgrade Data firmware: 8016-mfgdat6g-xxxxxxxxx.rom**

	Old Version	New Version
Controller Version	1.52 2015-11-20	1.54 2016-11-23
Boot Code Version	1.52 2015-11-20	1.54 2016-11-23
MBR Version	1.52 2015-11-20	1.54 2016-11-23
Expander Version	14.BD.00.09-20121017	14.BD.00.09-20121017
Expander Data Version	Mfgdat6g-20120907	Mfgdat6g-20120907
Release Date	JAN 12, 2016	MAR 16, 2017
New	1.Add Delay For to PHY Stable Function for Seagate HDD	1. Add EPC Supported. 2. Add Security Encryption Disk SED Function. 3. Add Clone Disk Function.
Fixed		
Modification		
Remove		4. Remove HTTP guest Account.