

Proware Technology Corp.  
 Technical Support Team  
 Firmware Release Notes

**Model: SASII to SASII /SATAIII 12/16/24/42 CHL (LSISAS2116)  
 For: EP-2123S-S6S6 / EP-3163S-S6S6 / EP-2243S-S6S6 /  
 EP-4423S-S6S6 series.**

**Important notes:**

- 1. Please update BOOT module first.**
  - (1) Upgrade Boot module: 8366BOOT-xxxxx.bin**
  - (2) Upgrade firmware: 8366-xxxxxx.bin**
  - (3) Upgrade Expander firmware:8016-x.xx.xx.xx-xxxxxxxxx.fw**
  - (4) Upgrade Data firmware: 8016-mfgdat6g-xxxxxxxxx.rom**

	<b>Last Version</b>	<b>New Version</b>
Controller Version		1.49 2010-04-26
Boot Code Version		1.49 2010-04-26
<b>Expander Version</b>		7.BD.00.99-20110420
<b>Expander Data Version</b>		Mfgdat6g-20110420
<b>Release Date</b>		MAY 4, 2011
<b>New</b>		1. Formal release.
<b>Fixed</b>		
<b>Modification</b>		
<b>Removed</b>		