

UNIFOSA CORP.

Technical Support Team

Software Release Notes

Model: proNAS 3.1.XX

For: EN-2123S6T-RQX / EN-3163S6T-RQX / EN-2126JS6T-SQX /
 EN-3166JS6T-SQX / EN-2120A6T-PDC / EN-3160A6T-PDC /
 EN-2800S6T-CM / DN-500A6T-CM / DN-500A6T-CQC /
 EN-1400A6T-CQC / EN-2126JSCT-SQX / EN-3166JSCT-SQX /
 EN-3166JS6T-RQX / EN-3166JSCT-RQX

3.1.02(2017-2-3 10:44)	
Release Date	FEB 03, 2017
Module	Change Note
System Manager	BUG Fixed After default volume group init. network restart cause mysql service stop
GUI	MOD Modify 10 second countdown to 20 second countdown when create a default volume group.
Service Manager	BUG webDAV service enable or disable, the progress bar/message will not close
Back Manager	BUG RDX RESTORE does not proceed for second cartridge.
Plugin Manager	<ul style="list-style-type: none"> - MOD Use virtual MAC address for public interface instead of sub-interface - NEW Support new plugin app Transmission - NEW Support new plugin app DLNA
System	<ul style="list-style-type: none"> - BUG Fixed not allow digital number to be the first character of login name when creating account - BUG Fixed http of webdav service can not start after upgrading - BUG Update net-snmp version to 5.7.3 - MOD Modify iSCSI target attribute, emulate_caw default value set to 0 - MOD Modify LSI RAID manager. Getting a correct start slot number for disks that are from NAS or JBOD - MOD mke2fs version to 1.43.3