

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: U3 SCSI to EIDE 16 CHL. (i80321)(6160)

For: SB-3160SI series.

Important notes:

- 1. Update from 1.36 and earlier firmware, Ethernet config must be saved again.**
- 2. Please update BOOT module before upgrade this version.**
 - (1) Upgrade Boot module: 6160BOOTxxxxx.bin**
 - (2) Upgrade firmware: 6160xxxxxx.bin**

	Last Version	New Version
Version No.	1.36 050411	1.39 060308
Date		March 24, 2006
New		1. Added Stagger power on control function. 2. Added RAID 1(1+0) with initialization function.
Fixed		1. Fixed Ethernet problem (Browser and Telnet can not connect). 2. Fixed FAN failed and recovered issue. 3. Fixed Hitachi 500G HDS725050KLAT80 hot-plug issue.
Modification		1. Display SMART status in drive status. 2. Mail SMTP port settable.
Removed		