

Proware Technology Corp.
 Technical Support Team
 Firmware Release Notes

Model: SCSI to SATA-2 4 / 8 / 12 / 16 CHL. (IOP348) (6373)
For: EP-1403-SA3 / EP-2803E1-SA3 / SB-2125E1-SA3 /
SB-2123E1-SA3 / SB-3163E1-SA3 / EP-T803E1-SA3 series.

Important notes:

1. Please update BOOT module first.
 - (1) Upgrade Boot module: 6373BOOT-xxxxx.bin
 - (2) Upgrade firmware: 6373-xxxxxx.bin

	Last Version	New Version
Version	1.49 2011-04-14	1.50 2012-03-12
Boot Code Version	1.49 2011-04-14	1.49 2011-04-14
Release Date	APR 27, 2011	APR 13, 2012
New	1. Formal Release.	1. Add Set Hitachi, WDC, Seagate SATAIII 6G HDD Negotiation Rate. 2. Add Slot Information of SATA HDD Rotation Rate Display. 3. Add Failed Disk Always Alarm Status.
Fixed		1. Resolved NEW SMART HDD TEMP for SMART HDD Temperature Value Error in EP-1403-SA3, EP-2803E1-SA3, EP-T803E1-SA3. 2. Resolved Foreground Initialize Display Percentage Error.
Modification		
Removed		