

Proware Technology Corp.
Technical Support Team
Firmware Release Notes

Model: SAS 3Gb/s to SATA-2 4/8/12/16 CHL. (IOP348) (6573)
For: EP-1403-S3A3 / EP-2803E1-S3A3 / SB-2123E1-S3A3 /
SB-3163E1-S3A3 / EP-T803E1-S3A3 series.

Important notes:

- 1. Please update BOOT module first.**
 - (1) Upgrade Boot module: 6573BOOT-xxxxx.bin**
 - (2) Upgrade firmware: 6573-xxxxxx.bin**
 - (3) Upgrade MPT firmware: 1064A4MPT-x.xx.xx.xx.bin**

	Last Version	New Version
FW Version	1.49 2011-01-26	1.49 2011-04-14
Boot Version	1.49 2011-01-26	1.49 2011-04-14
MPT Version	1064A4MPT-0.17.96.18	1064A4MPT-0.17.96.18
Release Date	Feb 22, 2011	May 16, 2011
New	1. Formal Release.	
Fixed		1. Fixed SATAIII issue
Modification		
Removed		