

UNIFOSA CORP.
Technical Support Team
Firmware Release Notes

Model: SASII to SASII /SATAIII 12/16/24/42 CHL
For: EP-2123J(JD)-S6S6 / EP-3163J(JD)-S6S6 / EP-2243J(JD)-S6S6
/ EP-4423J(JD)-S6S6 / EP-4643J(JD)-S6S6 Controller
Expander series.

Important notes:

- 1. Please update module first.**
 - (1) Upgrade Expander firmware:8016-x.xx.xx.xx-xxxxxxx.fw**
 - (2) Upgrade Data firmware: 8016-mfgdat6g-xxxxxxx.rom**

	Last Version	New Version
Expander Version	14.BD.00.09-20121017	14.BD.00.09-20121017
Expander Data Version	Mfgdat6g-20120907	Mfgdat6g-20150608
Release Date	JAN 25, 2013	OCT 07, 2015
New	<ol style="list-style-type: none"> 1. Add EP-4643J/JD-S6S6 for Power State Control (Need Hardware Supported). 2. Add the SES Command to Expander Reset Function. 	<ol style="list-style-type: none"> 1. .Add PRO-8088-24 backplane supported.
Fixed	<ol style="list-style-type: none"> 1. Resolved 3 Series 6G Controller in Event Log to Record [Temp Unknown Error]. 2. Resolved Some Case let to Each Expander Failed Problem at Redundant Mode. 	
Modification	<ol style="list-style-type: none"> 1. Change EP-4643 Series Expander Board SATA 6G Default Value. 	
Removed		