

UNIFOSA Corp.
Technical Support Team
Firmware Release Notes

Model: SASII to SASII /SATA2 12/16 CHL. JBOD (LSI SAS 2x36)
For: EP-2126J-S6S6 / EP-3166J-S6S6 / EN-2126JS6H /
EN-3166JS6H Series.

Important notes:

- 1. Upgrade firmware: sas2xfwxxx.fw**

	Last Version	New Version
Version	0.0.8	0.1.2A
Release Date	DEC 30, 2011	OCT 21,2013
New	<ol style="list-style-type: none"> 1. Add space character for model name setting. 2. Add maxphyrate get command to check disk phy rate. 3. Add backplane CPLD version check, Combine 16bay 6GB JBOD NAS new and old backplane. 	
Fixed	<ol style="list-style-type: none"> 1. Fixed 3GB JBOD NAS chain 6GB JBOD cannot booting issue. 2. Fixed Seagate SATA III ST500DM002 compatible issue. 	<ol style="list-style-type: none"> 1. Fix "Hardware Monitor temperature field" empty slot temperature will show real value (not "zero") connect with Areca. 2. Fix "Disk value start" function , connect LSI RAID Card ,it can show slot 0 start or slot 1 start in MSM 3. Connect Areca Model , slot number always start "1" in areca web GUI
Modification		
Removed		