

UNIFOSA CORP.

Technical Support Team

Software Release Notes

Model: proNAS 3.1.XX

For: EN-2123S6T-RQX / EN-3163S6T-RQX / EN-2126JS6T-SQX /
 EN-3166JS6T-SQX / EN-2120A6T-PDC / EN-3160A6T-PDC /
 EN-2800S6T-CM / DN-500A6T-CM / DN-500A6T-CQC /
 EN-1400A6T-CQC / EN-2126JSCT-SQX / EN-3166JSCT-SQX /
 EN-3166JS6T-RQX / EN-3166JSCT-RQX

3.1.02SP4(2018-1-4 18:35)	
Release Date	JAN 18, 2018
Module	Change Note
Storage Manager	BUG Thin provision volume extend size counting error MOD Logic volume extend size over 95% of total VG size forbidden MOD Support LSI RAID creation using two port enclosure chaining JBOD MOD using dd disk device before create RAID in SoftRAID Mgr (mdmgr)
Backup Manager	BUG Duplication Backup allow using Chinese folder
File Manager	BUG Allow enable File Manager service to delete file when WORM function enable BUG Privileges of folders created through File Manager should be consistent with folders created through Samba under Windows.
GUI	MOD Modify RAID foreground initialization message.
System Manager	MOD Support underline character in NAS host name.
Plugin Manager	MOD Modify HA from 3 nodes Active-Active mode to 2 nodes Active-Standby mode