

Proware Technology Corp.  
Technical Support Team  
Firmware Release Notes

**Model: EPICA PSUN Series (80331-500)**

**For: EP-2126-SS, 3166-SS/SA3 Series.**

**Important notes:**

- 1. Since firmware version 1.30, no longer work with proRAIDMgr.**

	<b>Previous Version</b>	<b>New Version (YYYY/MM/DD)</b>
<b>Version</b>	<b>1.23 (2009/04/16)</b>	<b>1.30 (2009/06/08)</b>
<b>Release Date</b>		<b>June 12, 2009</b>
<b>proRAIDMgr Version</b>	<b>1.3.4</b>	<b>Not available</b>
<b>New</b>		1. Added Flex GUI support. 2. Added SMART info support. 3. Added SATA spin up delay setting. 4. Added task priority info in the array status menu.
<b>Fixed</b>		1. Fixed system hangs after set Ethernet configuration. 2. Fixed R6 rebuild stop in 0%. 3. Fixed DVR (DX-TL2500) can't detect the volume.
<b>Modification</b>		
<b>Removed</b>		